01 P E G T MAY 0 5 2004 W TRADEMARK OF THE TOTAL OF THE T

PATENT B

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)
Toru SUZUKI	) Examiner: D. Ben Esplin
Application No.: 09/965,801	) Group Art Unit: 2851
Filed: January 6, 2004	)
For: SCANNING EXPOSURE APPARATUS AND METHOD	) May 5, 2004
U.S. Patent No. 6,674,509 B2	) : )
Issued: January 6, 2004	: Certificate MAY 1 0 2004
The Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450	MAY 1 0 2004 of Correction

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentee requests that a Certificate of Correction be issued by the Patent and
Trademark Office due to an error which appears in the printed patent as a result of Patent and
Trademark Office mistakes and a mistake of a minor nature which is not the fault of the Patent
and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

**Attention: Certificate of Correction Branch** 

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentee

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC\_MAIN 164937v1

# Staple Here Only!

## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,674,509 B2

**DATED** January 6, 2004

Toru SUZUKI INVENTOR(S):

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 1:

Line 60, "generate" should read -- generated --.

### COLUMN 4:

Line 11, "According" should read -- According to --. Line 47, "interface" should read -- interface, --.

### COLUMN 6:

Line 39, "i-lines" should read -- i-lines) --.

### **COLUMN 8:**

Line 39, "magnification a" should read -- magnification  $\alpha$  --. Line 46, "and t e" should read -- and the --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,674,509 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,674,509 B2

DATED : January 6, 2004

INVENTOR(S): Toru SUZUKI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 9:

Line 10, "value c" should read -- value  $\varepsilon$  --.

Line 39, "perpendicular of" should read -- perpendicular to --.

Line 50, "exposure" should read -- exposure method --.

Line 67, "a to" should read -- a variance to --.

### COLUMN 10:

Line 18, "shots," should read -- shots --.

### COLUMN 11:

Line 67, "chip J" should read -- chip --.

### COLUMN 13:

Line 25, "exposure p" should read -- exposure --.

Line 39, "operation of the manufacturing line in this system, the" should be deleted.

### COLUMN 14:

Line 56, "shorted," should read -- shortened, --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,674,509 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

FORM PTO 1050 (REV. 3.82)